

Sta of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program Report Date February 15, 2006

Supervisor ABH

Mine Name: Asphalt Ridge

Permit number: M/047/022

Operator Name: Uintah County Road Department

Inspection Date: February 9, 2006

Time: 10:45 AM to 12:00 PM

Inspector(s): Paul Baker

Other Participants: Alan Propp and Alberto Santiesteban (Black Sands Energy), Matt Crockett (Pruitt and Gushee representing Wembco and Jim Barnes), Quentin Johnson (Uintah County Road

Department), Jim Ableggen (Uintah County Commission)

Mine Status: Active Weather: Partly cloudy, 30's, 0-6 inches

of snow

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	\boxtimes		
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control	\boxtimes		
4. Deleterious Material	\boxtimes	\boxtimes	
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads,			
highwalls, shafts, drill holes)			
8. Water Impoundments	\boxtimes		
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other	\bowtie		

Purpose of Inspection:

Black Sands Energy Company has set up a tar sands processing facility on Uintah County's permitted area, and I wanted to see the operation and whether there were any concerns.

Inspection Summary:

4. Deleterious Materials

The tar sands processing operation uses hexane and pentane, and there were 10 barrels of pentane and five barrels of hexane on the site (Photo 4). These were not stored on a lined area, but overland flow would not leave the site. There were also some empty barrels. I confirmed that the Division of Water Quality will not require a permit for this operation, and they did not indicate a liner would be needed for the area where these chemicals are being stored. I also called Darrin Brown of the Tri-County Health Department to let him know about the operation.

12. Other

Equipment brought in for this extraction operation consists of the processing facility (Photo 1), an office trailer (Photo 2), an oil tank (which I was told has never held oil) (Photo 1), an underground tank to hold runoff water from the processing facility, a conveyor (Photo 1), a fuel tank, the pentane and hexane mentioned above, and miscellaneous other equipment and tools.

Inspection Date: February 9, 2006; Report Date: February 15, 2006

Page 2 of 2 M/047/022

The processed sand is being stored on a tarp (Photo 3). I could smell hydrocarbons in the sand, and the people from Black Sands said this was because the sand had not been fully processed to recover all the volatile chemicals.

Conclusions and Recommendations:

Black Sands had intended to set up this operation on the permit area for Wembco, but it is definitely in Uintah County's disturbed area. Therefore, Uintah County is ultimately responsible for any problems at this site. I do not believe the county was aware of the potential liability.

Black Sands is required by their lease with the land owner to be completely off the property by March 8, 2006.

This tar sands extraction operation is not included in Uintah County's Notice of Intention to Commence Large Mining Operations, and although the facilities are not permitted, I am reluctant to take enforcement action for the following reasons: 1. Most of the facilities are portable and could be easily removed. 2. This is a temporary situation. 3. The county is trying to promote economic development, including extraction of oil from tar sand. 4. The agreement between the land owner and the operator of the pilot facility is very strict and requires testing of the waste sand for a wider range of parameters than was required by the Department of Environmental Quality for an adjacent operation. 5. The amount of the Board Contract with the county for reclamation of the county's mine area is greater than the liability for reclamation of the mine by \$30,500. This would be adequate for reclamation of these facilities.

__ Date: 3/13/06

Inspector's Signature

PBB:pb

Quentin Johnson, Uintah County Road Department

Attachment: Photos

 $P:\GROUPS\MINERALS\WP\M047-Uintah\M0470022-Uintah\AsphaltRidge\final\ns-02092006.doc$

ATTACHMENT

Photographs

M/047/022, Asphalt Ridge Mine, Uintah County Road Department

Inspection Dated: February 9, 2006; Report Dated: February 15, 2006




Photo 1. An oil storage tank and processing facility.



Photo 2. The trailer and some of the other facilities associated with the pilot operation. The conveyor is part of the existing processing operation.



Photo 3. Waste sand.



Photo 4. Barrels of pentane and hexane.